

PRESALTING ROUTES – 2016/17

ROUTE: TREDEGAR

DEPOT: NEW VALE

NOTE: ENSURE THAT ALL ROUNDABOUTS ON ROUTE ARE COMPLETELY GRITTED.

1. NOT SALTING: Proceed from Central Depot turn left to roundabout, take 1st exit to

14. **START SALTING:** Proceed along Attlee Way to junction Queen Victoria Street, left up Gainsborough Road, 2nd left Walter Conway Avenue, left Gainsborough Road to junction Attlee Way, left along Attlee Way along Queen Victoria Street, left through

26. START SALTING: Turn left into Rhoslan to junction Ysguborwen. STOP SALTING.
27. NOT SALTING: Proceed to junction Ysguborwen / Chartist Way.
28. START SALTING: Proceed down Chartist Way to junction Dukestown Road. STOP SALTING.
29. NOT SALTING: Proceed to junction Glanhowy Street/St Luke's Road, turn left.
30. START SALTING: Proceed along Glanhowy Street, Scwrfa Road to junction Dukestown Road. STOP SALTING.
31. NOT SALTING: Proceed to Waun-y-Pound Industrial Estate (Alfred Teeves), turn right.
32. START SALTING: Turn right proceed past Alfred Teeves turn left, proceed to roundabout, complete roundabout take 4th exit return past Alfred Teeves to junction A4047 turn right along A4047 turn right at Robert Price's proceed to roundabout take 1st left proceed to New salt Barn turn and return to roundabout take 1st left New Vale Depot – Fill with Salt.
33. NOT SALTING: Return to Central Depot Via H.O.V. Road.
34. START SALTING (Mini Gritter) - Turn off Poplar Road into Fields Road, turn left along Oakfield road, proceed to school entrance. STOP SALTING